

ABSTRACT

A method for forming a shiplap edge in a duct board comprises the steps of: molding a shiplap edge in a first duct board made of mineral fiber or mineral wool, so that the molded shiplap edge has a molded edge thickness, and machining the molded shiplap edge to a desired
5 machined edge thickness that is less than the molded edge thickness.